



**Location: Oasis Academy Ryelands  
Oakley Road**

**Project: School Crossing Patrols**

**Stage 1 Road Safety Audit**

REV	ISSUE STATUS	PREPARED BY/DATE	CHECKED BY/DATE	APPROVED BY/DATE
1	DRAFT	DG 08 July 2025	UF 08 July 2025	
	FINAL	DG 08 July 2025	UF 08 July 2025	DSG 09 July 2025

**Date: July 2025**

**Report produced for: Citizensense on behalf of the London borough of Croydon**

**Report produced by: DSG Events and Traffic Management**

Citizensense  
86-90 Paul Street  
London  
EC2A 4NE  
07506 739326



## Contents

1	Introduction .....	3
2	Proposals and Information Provided .....	4
3	Documents and Drawings Provided .....	4
4	Collision data .....	4
5	Documents and Information Not Provided .....	4
6	Previous Road Safety Audits .....	4
7	Departures from Standards .....	4
8	Matters Arising from this Audit .....	5
9	Audit Team Statement .....	6
10	List of drawings and documents provided to the Audit Team.....	7
11	Location plan .....	9

### [Appendices](#)

[One. List of Drawings and Documents Provided to the Audit Team](#)

[Two. Location Plan](#)

## 1 Introduction

This report is a Stage 1 Road Safety Audit (RSA) carried out on an existing crossing point on Oakley Road outside the Oasis Academy Ryelands main entrance, with a review of options for the site following the potential removal of the School Crossing Patrol. The Audit was carried out on behalf of London Borough of Croydon. The RSA team present were:

██████████

Team Leader  
Senior Engineer

██████████

Team Member  
Principal Engineer

We confirm that no member of the Audit Team has been involved with the design process and that at least one member of the Audit Team holds the National Highways Certificate of Competency.

The site visit was carried out on Monday 7<sup>th</sup> July 2025 between the hours of 20:30-20:45hrs. The weather during the site visit was sunny and the carriageway surface dry. Traffic flows were busy, with a low number of pedestrian and cyclist movements observed during the visit.

The terms of reference of the RSA are as described in the Design Manual for Roads and Bridges GG 119 - Revision 2. The RSA team has examined and reported only the road safety issues of the scheme as presented and has not examined or verified the compliance of the design to any other criteria.

All the problems described in this report are considered by the RSA auditor to require action in order to improve the safety of the scheme and minimise collision occurrence. A road safety audit response report should be produced collaboratively by the design organisation and Overseeing Organisation to respond to the problems detailed within this report.

The Scheme Promoter must respond to the problems and accompanying recommendations in Section 2. The Audit Team will acknowledge the Scheme Promoter's response, and this will state which problems are not resolved and, if considered necessary, recommend a separate exception report. The Scheme Promoter and Safety Audit Team Leader must complete and sign this report. The satisfactory completion of this document is vital in case of future litigation against the County Council.

## **2 Proposals and Information Provided**

The scheme proposes to review the layout of the crossing facility, with the concerns being the removal of a previous school crossing patrol from the location.

## **3 Documents and Drawings Provided**

A list of information provided to the team is included in **Appendix Two**.

## **4 Collision data**

No collision data has been supplied to the Audit Team to review.

## **5 Documents and Information Not Provided**

The following information has not been provided to the Audit Team:

- Traffic Counts
- Pedestrian Surveys

## **6 Previous Road Safety Audits**

No previous Road Safety Audits have been forwarded to the Audit Team to review.

## **7 Departures from Standards**

No Departures from Standards have been provided to the Audit Team.

## **8 Matters Arising from this Audit.**

There were no issues identified during this Stage 1 Road Safety Audit.

DRAFT

## 9 Audit Team Statement

We certify that the audit has been carried out in accordance with the requirements set out in DMRB GG119.

### AUDIT TEAM LEADER



Signe



Date: 08 July 2025

### AUDIT TEAM MEMBER(S)



Signed



Date: 08 July 2025

## **APPENDIX ONE**

### **10 List of drawings and documents provided to the Audit Team**

DRAFT

## LIST OF DRAWINGS PROVIDED TO THE AUDIT TEAM

### Drawings

#### Drawing No.

- N/A

### Documents

Brief for Road Safety Audit - School Crossing Patrols

6 x Safety Assessments SCP

DRAFT

## APPENDIX TWO

### 11 Location plan

DRAFT

## LOCATION PLAN



DRAFT